

VEHICLE INSPECTION REPORT

572354

HONDA HRX537 C4HYEA

Inspection

Vehicle

VAT	Plus VAT
V5	Not Present

Details

Reg. date	Mileage	TBC	Colour
Year	Fuel Type	VIN	MAGA2572354

MOWER, HONDA GCVX 200 PETROL ENGINE *FOR SPARE OR REPAIR - PULLS BUT CORD DOES NOT RETRACT, HANDLE BROKE*

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

